

28 November 2023

P (03) 546 0200 E rebecca.thiessen@ncc.govt.nz nelson.govt.nz

Kia ora,

BROOK STREAM - ROCK ARMOURING OF STREAM BANK

During the August 2022 weather event some of Nelson's rivers and streams suffered stream bank or stream bed erosion. We need to remediate some of these areas to reduce the chance of the river flooding again and damaging Council assets and/or private property.

We have identified an area of bank erosion located behind 125C Tasman St. This bank will be gently regraded, then a small amount of rock will be placed along this affected bank to prevent future erosion. The required rock will be transported along private access ways from Tasman Street, with a Traffic Management Plan in place.

This work will occur from Wednesday 29 November 2023. It is likely to take 1-2 days to complete (weather dependent).

The approximate area of repair is shown in Figure 1 below.



Figure 1: Taken from Top of the South Maps.





If you have any questions or queries in relation to this work, please feel free to contact either me, by phone on 021 350763 or by email on rebecca.thiessen@ncc.govt.nz, or Marc Jary by phone on 027 3886077 or by email on mjary@nelmac.co.nz.

There may be some noise associated with this work, so we apologise for any inconvenience that this may cause.

We appreciate your patience while this work is completed.

Yours sincerely,

Rebecca Thiessen

Project Manager
Nelson City Council